

Axe-Fx II Firmware Release Notes

1.02

Fixed popping when switching between certain amp models.

Fixed X/Y not working properly in Cabinet block.

Improved Rotary block.

Added X/Y copy feature. To copy all parameters from "X" to "Y" double-click "Y". Likewise double-click "X" to copy from "Y".

Added Tube Pre model.

1.01

Initial production release.