



MFC-101 MARK IIIFIRMWARE RELEASE NOTES - IMPORTANT! READ BEFORE UPDATING!

The MFC-101 Mark III is not compatible with firmware for the Mark II or original MFC-101. Please ensure that you have selected the correct file for your unit from the firmware zip file.

Release 3.03

Apr 9, 2014

WHAT'S NEW?

- Added Axe-Fx II XL support. Please be sure to select the correct model in the SETUP menu of the MFC after updating.
- Added FASLINK support for the MFC-101 Mark III. Be sure to select the correct PORT in the MIDI menu of the MFC after updating. Please also note that if you're using an Axe-Fx II XL, you must also select the desired MFC port ("EtherCON" or "FASLINK") in the I/O:MIDI menu of the Axe-Fx II XL.

* * *

RELEASE NOTES FOR OLDER VERSIONS

v3.02

- Fixed bug in external switches where XS 3 and 4 weren't working correctly.

v3.01

- Solved an issue with Hold Tap for Tuner not working on switches except #1 and #17
- Solved an issue with BANK UP and BANK DOWN not repeating when the footswitch is held.

v3.00

First public release. The MFC-101 Mark III is not compatible with firmware releases prior to version 3.00, (December 2014)

In comparison to older versions, 3.0 adds the ability to assign SCENE 1/2 TOGGLE and VOL INCR, VOL DECR to Axe-Fx IA switches.

* * *