

Axe-Fx III Firmware Release Notes

1.05

Fixed MIDI bank select.

Fixed Scene Copy function not copying Amp block bypass states.

Fixed can't select Amp type when creating a new preset if the previous preset had the Amp block channel as anything other than 'A'.

Fixed External Controller initial values not being applied and garbage values in any of these controllers that are not assigned.

Added ability to route block when Layout is zoomed out.

Added Input Source select to ADSR and Envelope in Control block.

1.04

Fixed low-cut and high-cut filters not working in Multitap Delay block.

Fixed Amp blocks bypass states not being preserved across preset changes.

Fixed Tone Match block Smoothing parameter not working.

Fixed Quad Tape Delay missing modifier for Motor Speed (formerly labeled Tape Speed).

Fixed MIDI CC Channel changes not responding above values of 3.

Various GUI enhancements and improvements.

1.03

First public firmware release.