



MFC-101 MARK III FIRMWARE RELEASE NOTES - IMPORTANT! READ BEFORE UPDATING!

The MFC-101 Mark III is not compatible with firmware for the Mark II or original MFC-101.
Please ensure that you have downloaded the correct file for your unit.

Release 3.01

Jan 9, 2014

WHAT'S NEW?

- Solved an issue with Hold Tap for Tuner not working on switches except #1 and #17
- Solved an issue with BANK UP and BANK DOWN not repeating when the footswitch is held.

* * *

RELEASE NOTES FOR OLDER VERSIONS

v3.00

First public release. The MFC-101 Mark III is not compatible with firmware releases prior to version 3.00, (December 2014)

* * *